



Chalford Vale Recreation Ground

23 April 2026

by CP Nathanail
Land Quality Management Ltd


Chalford play area looking east from entrance



LQM1607

Chalford play area

notices at entrance



LQM1607

STROUD DISTRICT COUNCIL

Chalford Parish Council


Public Meeting – Investigations at Chalford Valley Playing Field

We would like to invite interested parties to a public meeting that will be held at Christ Church, London Road, Chalford on 23rd April 2026 between 19:00 and 20:15. The meeting will be attended by representatives from Chalford Parish Council, Stroud District Council and an independent Environmental Consultant who has been involved in the investigation process.


The purpose of the meeting is to provide an update on the ongoing investigation at Valley Playing Field. As previously communicated, the playing field has been closed, as a precaution, whilst on-going investigations take place. The investigations relate to the identification of Cement Bound Asbestos (CBA), as well as other materials such as broken glass and pottery being brought to the surface by mole activity.

Members of the public are invited to submit questions in advance by 18:00 on Monday 20th April 2026. This will help ensure we are able to respond as fully as possible during the meeting. Please submit questions to: clerk@chalford-glos.gov.uk



We will endeavour to provide written minutes of the meeting and answer any further questions within two weeks following the meeting. This will be published on the Chalford Parish Council website www.chalford-glos.gov.uk



View of play equipment looking east





View of eastern end table tennis table and goalposts




Molehill Location MH-1

close to asymmetric bars





LQM1607



7

Molehill Location MH-2



between swings and asymmetric bars



LQM1607


Molehill Location MH-3

next to spaceship climbing frame





LQM1607

Molehill Location MH-4 between spaceship and zip wire tripod




Molehill Location MH-5

next to off ramp of zip wire




Molehill Location MH-6 along zipwire alignment




Molehill Location MH-7

in grass outside football pitch




Molehill Location MH-8

in middle of football pitch





LQM1607




14

Molehill Location MH-9 towards eastern end of football pitch




Molehill Location MH-10 at western end of football pitch



Glass shard next to bench by river Frome



Fragment of [potential asbestos containing] material by river Frome



LQM1607

Close up of fragment



APPENDIX 5 LABORATORY RESULTS: RESPIRABLE DUST